

Inspection Report

A. GENERAL INFORMA	ATION:				
Report No.:		BOOKING NO .:			
Client:			Со	untry	UK
Supplier:					
Product Description:	Blue Baseball caps				
P.O. NO.:	NBR20150418				
P.I. NO.:	NBR20150418				
SKU NO. :	SKU-MS99013-XJ SKU-MP17122-QZ SKU-MC62650-QZ				
P.O. Quantity:	MS99013-XJ:24600pcs/123ctns MP17122-QZ:2000pcs/10ctns MC62650-QZ:1000pcs/5ctns			DEWALT	STANLEY
Qty Presented:	MS99013-XJ:24600pcs/123ctns MP17122-QZ:2000pcs/10ctns MC62650-QZ:1000pcs/5ctns			0	
Service Performed:	Pre-Shipment Inspection				
Inspection Date:	2015/4/18				
Inspection Location:	Ningbo				
Inspector(s):	JIMMY				
Sample available:	Yes				

B. Inspection Summary: FAILED PASSED PENDING N.A. REMARK Ρ 1. Quantity 2. Style , material , color: Ρ Ρ 3. Workmanship/appearance/function Ρ 4. Packing Ρ 5. Marking/label Ρ 6. Data measurement/field tests Ρ 7. Client Special Requirement

C. Rei	mark:						
Probl	em Remarks:						
1	Whole inspection was based on approved samples						
Gene	ral Remarks:						
2	Barcode scanning are pass						





CONCLUSION:

PASSED

1. Quantity Check:						
Art. No.	Order Qty.	Present	ted PCS	Presented CTNS		
	Order Ory.	Packed	Not Packed	Packed	Not packed	
SKU-MS99013-XJ	24600	24600	0	123	0	
SKU-MP17122-QZ	2000	2000	0	10	0	
SKU-MC62650-QZ	1000	1000	0	5	0	
Total:	PCS	PCS	PCS	138CTNS	CTNS	
Result:	Passed					
Remark:						

2. PRODUCT CONFORMITY:						
CONFORMITY	YES	NO	PENDING	REMARK		
2.1 Style conformity:	Р					
2.2 Material conformity:	P					
2.3 Color conformity :	P					
Remark:						
Whole inspection was based on approved samples						

3. WORKMANSHIP APPEARANCE / FUNCTION INSPECTION FINDINGS:								
Inspection standard:	ANSI/A	ANSI/ASQ Z1.4		CL	Accepted	Defects Found		Result
Sampling Plan:	Normal	Single	Critica	l: 0	0	0		PASSED
Inspection Level:	Level II		Major:	2.5	14	0	0	
Sample Size:	315		Minor:	4.0	21	10		PASSED
		PASSED FAILED PENDING				\square	W	THIN AQL
Inspection found					Due to		BE	Yond Aql
							R	EMARKS
Inspected Samples Size and Cartons								
Item No.	Quantity	Cartons		Iten	n No.	Quantity		Cartons
SKU-MS99013-XJ	280	11		SKU	J-MP17122-Q2	Z 23		3
SKU-MC62650-QZ	11	2	2		/	/		/



Page 2 of 36




Inspection

www.gb-inspection.com

Address: Room 203 Ben Li Er Buliding of No.1 xing tai Road ,Ren he Town ,Bai yun District, Guangzhou,Guangdong, China TEL: 86-20-28965223 86-13631329406 Email: gbinspection@163.com

Item No.	Ref. Pic.	Defects Description:	Defects Description: Critical Major		Minor	
MC62650-QZ	3-1~3	Thread end			3	
	3-4	Thread end			1	
MP17122-QZ	3-5	Thread end			1	
IVIF 17122-QL	3-6	hread end 1				
	3-7	Foreign matter 1				
	3-8	Thread end			1	
MS99013-XJ	3-9	Thread end			1	
	3-10	Thread end			1	
		Total Defects Found:	0	0	10	
Max Defects Allowed: 0 14 21						
		Sample Size:	315	315	315	
Remarks:						


Note: A Defective is defined as a unit of product that contains one or more defects. A Defect is defined as any non-conformance of the inspected unit of product with specified requirements. A single defect is taken into account per each defective unit; only one most serious defect is taken into account per each defective unit.





Page 3 of 36





Page 4 of 36



4. PACKING				
	YES	NO	PENDING	REMARK
4.1 if package of carton is scientific rationality	Р			
4.2 Individual packing	Р			
4.3 Export packing conformity	Р			

5. MARKING/LABEL				
	YES	NO	PENDING	REMARK
5.1 Bar code:	Р			
5.2 Shipping mark conformity:	Р			SEFIT (HA)
5.3.Side mark conformity:	Р			- + + * * E
5.4 Main label :				NA AND
				010 *

Page 5 of 36



Inspection www.gb-inspection.com

6. Data measurement/Field Tests (as applicable for specific product/order)

6.1: Size and weight of carton, product, inner box.please see below record and pictures

6.2: Barcode scanning are Pass .please see below pictures


7. Client Special Requirement

Not Applicable

8. Informative Remark:	
8.1	
8.2	




Page 6 of 36






Page 7 of 36







Page 8 of 36





Page 9 of 36

Address: Room 203 Ben Li Er Buliding of No.1 榮益香港有限公司 xing tai Road ,Ren he Town ,Bai yun District, Guangzhou, Guangdong, China TEL: 86-20-28965223 86-13631329406 Inspection www.gb-inspection.com Email: gbinspection@163.com Weight of inner box 23. 24. 4.65 kg 25. inner box details Open inner box 26. 27. 28. Package details Unit package



Page 10 of 36





Page 11 of 36





Page 12 of 36






Page 13 of 36

没祭益香港有限公司Inspectionwww.gb-inspection.com


Address: Room 203 Ben Li Er Buliding of No.1 xing tai Road ,Ren he Town ,Bai yun District, Guangzhou,Guangdong, China TEL: 86-20-28965223 86-13631329406 Email: gbinspection@163.com





Page 14 of 36







Page 15 of 36

必樂益香港有限公司Inspectionwww.gb-inspection.com

Address: Room 203 Ben Li Er Buliding of No.1 xing tai Road ,Ren he Town ,Bai yun District, Guangzhou,Guangdong, China TEL: 86-20-28965223 86-13631329406 Email: gbinspection@163.com





Page 16 of 36





Page 17 of 36





Page 18 of 36





Page 19 of 36





Page 20 of 36





Page 21 of 36





Page 22 of 36

必樂益香港有限公司Inspectionwww.gb-inspection.com

Address: Room 203 Ben Li Er Buliding of No.1 xing tai Road ,Ren he Town ,Bai yun District, Guangzhou,Guangdong, China TEL: 86-20-28965223 86-13631329406 Email: gbinspection@163.com





Page 23 of 36





Page 24 of 36

Address: Room 203 Ben Li Er Buliding of No.1 榮益香港有限公司 xing tai Road ,Ren he Town ,Bai yun District, Guangzhou, Guangdong, China TEL: 86-20-28965223 86-13631329406 www.gb-inspection.com Inspection Email: gbinspection@163.com 113. With samples compared 114. With samples compared SKU-MS99013-XJ 3 Art NO .: 115. Main carton 116. Carton view SKU-MS99013-XJ Product - Baseball Caps SKU-MS99013-XJ Colour - Blue Product-Baseball Caps Quantity - 200 Colour - Blue Quantity - 200 Order Number - 4500931293/ Inbound number 8161695990 Order Number-4500931223/inbound number 3161625990

Carton No: /23 of 138 Carton No: /= 2 of 138 Shipping mark 118. Side mark

Gross Weight - 18 kgs Total Cartons- 138

117.

Gross Weight - 18 kgs

Total Cartons-138




Page 25 of 36






Page 26 of 36







Page 27 of 36





Page 28 of 36







Page 29 of 36





Page 30 of 36






Page 31 of 36

梁益香港有限公司

Inspection www.gb-inspection.com

Address: Room 203 Ben Li Er Buliding of No.1 xing tai Road ,Ren he Town ,Bai yun District, Guangzhou,Guangdong, China TEL: 86-20-28965223 86-13631329406 Email: gbinspection@163.com





Page 32 of 36








Page 33 of 36





Page 34 of 36







Page 35 of 36





The end of the Inspection Report



Page 36 of 36